

TILLAMOOK COUNTY REWITNESS

#253

$\frac{1}{16}$ COR.
E.

SEC.

$\frac{32}{5}$ T $\frac{15}{25}$

R 9 W., WM.

HISTORICAL:

B-278

F-41-60

BK 53" Pg 492

BK CL9 Pg 22

CONDITION FAIR


FOUND: SPRUCE STAKE BOTTOM

BOOK "53" Pg 492

COMMENTS: SPRUCE STAKE HAD SHARPENED POINT AND POSITION WAS GOOD -- REFER TO CALCS IN ROAD BIN #320 M-CORMICK LOOP ROAD

REWITNESS

1 SET 2" IRON PIPE WITH 3" BRASS CAP IN CONCRETE AT POSITION OF FOUND SPRUCE STAKE
84" Hat Section NORTH 1735



NEW ACCESSORY:

PP# E4-64 25 P85-R15	S 86° W 135 ⁵³ A	1974
PP# 26 P85-R16	S 80° E 213 ³ A	1974

COMMENTS: THE CENTER OF THE BRASS CAP IS BREAKING OUT DUE TO TRAFFIC 1974. THE CORNER IS LOCATED IN THE NORTH DRIVING LANE OF MAPES COUNTY ROAD (M-CORMICK LOOP ROAD).

IN THE PRESENCE OF:

A. DUNCAN G. URREY G. ARTHUR 1969
G. ARTHUR D. McNUTT 1974

DATE: 5-69

PHOTO#:

* = County corner tag affixed.

TITLE