

#281

TILLAMOOK COUNTY REWITNESS

1/4 N.W. 8 COR. 718 T 1 S R 10 W., WM.
4 S. E. 7

HISTORICAL: GLO 1510 Pg. 36 1857 SET Post


BOOK	PAGE	MAP
S3	496	B-183
P31	118	A-1995
H	67	
S3	152	

CONDITION	FOUND:	1 1/2" IRON PIPE
N. F.	30" HEMLOCK	N. 22° E. 40 LKS. GLO Pg. 36
FOUND ROTTEN STUMP ^{SCRIBING} _{IN PLACE}	24" HEMLOCK	N. 30° W. 15 LKS. GLO Pg. 36
NOT FOUND	24" HEMLOCK	N. 9° W. 23 LKS. H Pg 67
* FD. GOOD NOW 40"	12" HEMLOCK	N. 26° E. 16 7/8 FT. P 31 Pg 118

COMMENTS:

REWITNESS

1 SET 1 1/2" IRON PIPE WITH 3" BRASS CAP IN 10" TILE & CEMENT
 @ POSITION OF FD. 1 1/2" IRON PIPE
 60" Hat Section 15 WEST



NEW ACCESSORY:

* 10" HEMLOCK	S. 39° W. 26 2/3	1/4 S 7 BT CS
3-3:06 DM JVJ-Corner found	in good condition	Bearing Trees o.k.
Found additional scribing on side of this card.	rotten stump described	as found on reverse

COMMENTS: THIS CORNER IS LOCATED ± 400 WEST OF OCEANSIDE - CAPEMEARS ROAD & ± 30' WEST OF THE BOTTOM OF A SMALL GULLY.

IN THE PRESENCE OF: DAN MCNUTT GALE ARTHUR

DATE: 2-27-80 PHOTO#: NW10 6-74

* = County corner tag affixed.