

T1S R11W T1S R10W
 24 19
 25 30

TILLAMOOK COUNTY REWITNESS #318
 SEC. 24/19
 25/30 T 1S R 11-10W., WM.

RANGELINE COR.

1856=SET A POST
 1887= SET A BASALT STONE
 TISRIOW Pages 5 (1856) & 68 (1887)

HISTORICAL: GLO

Book	Page	MAPS
1	81	B-135
4	57	B-520
P-31	17 & 144	F-13-5
		F-13-29

CONDITION	FOUND:	
MISSING IN 1887	32" SPR. N47°E 334 ^{IKS}	GLO Page 5 1856
GONE 10-24-75	33" SPR. N25°W 334 ^{IKS}	GLO Pages 5 (1856) & 68 (1887)
GONE 10-24-75	4" SPR S14°W 13.1 ^{FT}	BK1 Pg 81 BK4 Pg 57
FD WITH FACE NOW 12" * 10-24-75	7" SPR S80°W 18.4 ^{FT} GONE 1-23-03	BK1 Pg 81 BK4 Pg 57
GONE 10-24-75	6" SPR S22°E 56.4 ^{FT}	BK1 Pg 81 BK4 Pg 57
GONE 10-24-75	18" SPR N14°E 37.6 ^{FT}	BK1 Pg 81 BK4 Pg 57
FD NOW 25" 10-24-75	20" SPR WEST 17.2 ^{FT} NOW 48 ²⁵ FT FD OK. 1-23-03	BK5 Pg 134
COMMENTS: FD WITH 60d SPIKE IN FACE 10-24-75	20" SPR NOBE	BK5 Pg 134

REWITNESS

1 SET 2" IRON PIPE WITH 3" BRASS CAP IN 10" TILE AND CEMENT
 "x" "x" LIGHT Post N.W. feet
 72" Hat Section ~~S~~ N 40° W 15 FEET
 ADDED 1-23-03

T1S
 R11W R10W
 S24/S19
 S25/S30
 RS 287
 1973

NEW ACCESSORY:

5/8" IR WITH YELLOW BEARS N. 55° 29' 40" E	PLASTIC CAP "CLM" 57.96 FEET	INC. PLS 293" 3-24-03 JDM
--	------------------------------	---------------------------

COMMENTS: THIS CORNER WAS LOCATED ON TOP OF A ± 12' BANK AND WAS RESET BY G.W.U. & W.G.A. UNDER NEATH OF OLD CORNER IN 1973. THE CORNER SET IS DESCRIBED ABOVE. OLD CORNER IS STILL IN PLACE ABOVE 1973 CORNER.

IN THE PRESENCE OF: (WGA) D. MCNUTT, WILLIAM GALE ARTHUR, 3
 K. DUNN

DATE: 10-24-75 PHOTO#: TITLE

* = County corner tag affixed.