

TILLAMOOK COUNTY REWITNESS #322

~~E~~/~~W~~ COR. 26/25 T 15 R 10 W., WM.  
DLC.#

26 * 25
Int. Pt.      Seaport

HISTORICAL: Books 1 P 59 Set 1 1/2" IP (1911)


1/4 IP	South 30 ft
1/2 IP	North 30 ft

CONDITION	FOUND: 1 1/4" IP NORTH 30° from 1/4 cor point
South PIPE MISSING: IS in ditch line	

COMMENTS:

REWITNESS

I SET Railroad Spike in ~~E~~ Netarts Road  
 "x" "x" " Post N.W. feet  
 " Hat Section S. E.



NEW ACCESSORY:

Power Pole	S 38° E 31.73	1/4 525 BTCS
Guy Pole	N 36° E 27.92	1/4 525 BTCS

COMMENTS:

IN THE PRESENCE OF: STAN SKINNER  
GALE ARTHUR

DATE: 5/19/65

PHOTO#: [unclear] [unclear] TITLE

\* - County corner tag affixed.

GWU