


TILLAMOOK COUNTY REWITNESS #336



W. 35 SEC. 34 35 T 15 R 10 W., WM.
 1/4 COR. 34 35 T 15 R 10 W., WM.
 E. 34

GLO-1856-S.D. SNOWDEN-SET POST- HEM 32" S 32° W 14 LKS GLO
 HEM 32" S 49° E B LKS PAGE 24

HISTORICAL: GLO-1890-A.P. WILSON-Found no 1/4 corner GLO
 PAGE 71

BK 28 P 14 = W.S. COATES = 1920 = MAP B-187 = Tied 1/4 corner 34 35

BK 4 P 33 = W.E. ANDERSON = 1926 = SET 2" Iron Pipe in place of old stake. Bear-
 ing trees still visible. NEW = 22" HEM N 63° 30' W 27.2
 FT'S = 22" HEM N 13° 00' W 21.1

BK 4 P 67 & BK 1 P 85 = W.E. Anderson = 1949 = Found 2" Iron Pipe MADE

NEW BEARING TREES 36" HEM S 10° 30' W 89.5' Previous Bearing Trees set in 1926 were cut down or blown over
 20" HEM N 81° 15' W 88.1
 MAP A-24 - W.E. Anderson = 1945 = Corner tied to Road // A-365 = R. WALKER = 1949 Found 2" Iron Pipe & 1 Bearing Tree


CONDITION FOUND:

BADLY RUSTED	2" Iron Pipe
FD GOOD 10-23-75	36" Hemlocks S 10° 30' W 69.5' NOW 40" on SOUTH SIDE OF HWY #131
FD GOOD 10-23-75	20" Hemlock N 81° 15' W 88.1' NOW 24" tree on NORTHSIDE HWY #131

HISTORICAL: MAP A-423 W.E. Anderson 1950 // MAP A-500 - W.E.A. - 1951 // MAP A-513 WEA.
~~COMMENTS~~ MAP A-831 JLC 1959 // MAP A-1104 JLC 1969 // Fd 1/4 corner 1952
 MAP A-1203 JLC 1964 Tied 1/4 cor. MAP A-1851 G. Collard 1969 2" IP

REWITNESS

1 SET 1" Iron Pipe inside of old 2" Iron Pipe
 4" x 4" x 48" Post W. WEST 1/2 feet



NEW ACCESSORY:

2" IP WITH 3" BRASS CAP IN 10" TILE AND CEMENT
 SET IN POSITION OF FOUND 1" IP INSIDE OF OLD 2" IP
 WHICH IS NOW LAYING ALONG SIDE MONUMENT.
 G. ARTHUR, D. McNUIT AND K. DUNN 10-23-75
 SET 86" HAT SECTION NORTH 1/2 FEET

COMMENTS: No New B.T.s' Needed
 Corner is located on top of north cut bank

IN THE PRESENCE OF: SA SKINNER
 GALE Arthur

DATE: 10-11-65

PHOTO: REC

TILLAMOOK COUNTY REWITNESS TITLE

* - County corner tag affixed.

OWN