

TILLAMOOK COUNTY REWITNESS #358

N.W. 9 SEC. 54  
COR. 819 T 25 R 9 W., WM.  
S. E. 5

HISTORICAL: G.L.O Pg. 16.117 ± 1857

BOOK	PAGE	MAPS
4	88	B-612
5	143	A-1350
53	342	F-26-17
1	96	

CONDITION GOOD FOUND: BRASS CAP IN CONCRETE

NOT FOUND	32" SPRUCE	S. 38° W. 11 LKS.	G.L.O Pg. 16
NOT FOUND	16" HEMLOCK	S. 44° E. 59 LKS.	G.L.O Pg. 16
NOT FOUND	24" SPRUCE	N. 47° E. 72 LKS.	G.L.O Pg. 16
NOT FOUND	24" SPRUCE	N. 19° W. 48 LKS.	G.L.O Pg. 17
NOT FOUND TANK HAS BEEN REMOVED	LEAD PLUG CORNER OF N.W. CORNER OF BOILER ROOM	N. 77° W. 101 02 FT.	BK 4 Pg. 88
FOUND GOOD	LEAD PLUG CORNER OF BOILER ROOM	S. 30° W. 57 5 FT.	BK 4 Pg. 88
FOUND GOOD	LEAD PLUG CORNER OF BOILER ROOM	S. 70° E. 87 0 FT.	BK 4 Pg. 88

FOUND DISCREPANCY IN BEARING & DIST.

LEAD PLUG IN REPORTED N. 89° E. 146 98' BK 4 Pg. 88  
LOADING PLATFORM ACTUAL S. 87° E. 149 00' NOW


REWITNESS

1 FD. 4" BRASS CAP IN CEMENT SET BY SOUND CONST & ENGINEER CO.

86" Hat Section

N. E.

10 FEET



NEW ACCESSORY:


COMMENTS: THIS CORNER IS LOCATED ± 20' SW OF D. STREET IN TILLAMOOK COUNTY INDUSTRIAL PARK.

IN THE PRESENCE OF:

GALE ARTHUR

DAN MCNUTT

DATE: 6-19-79

PHOTO#: 388

\* = County corner tag affixed.

TILLAMOOK COUNTY DEPT. OF REVENUE

TITLE