

TRUMAN
HARRIS
DLC
SEC. 8

TILLAMOOK COUNTY REWITNESS

#373

SEC. 8
COR. Truman Harrist 25 R 9 W., WM.
S. E. DLC.#

HISTORICAL: Bk S.3 Pages 78, 456-460
Bk 4 Page 91

MAP B-30 by W.E. Anderson 1931

MAP A-535 by W.E. Anderson 1952

MAP A-1036 by J.L. Carlich 1963

MAPS A-1135 & A-1131 by J.L. Carlich


FOUND:

CONDITION	
fair / rusting	1/4" Iron Pipe ± 3" below Road Surface Iron Pipe was plugged & Tacked
Good	Concrete Mon. N42°52'E 40 87
Good	Tele Pole 162 S32°11'E 35 70

COMMENTS: Spruce tree used in 1952 is now gone (April 1970)

REWITNESS

1 SET 2" Iron Pipe 24" long with 3" Brass Cap in Conc. & Tile
feet



* 96 " Hat Section E. EAST 175 Feet

NEW ACCESSORY:

* Power Pole SP-3 N22°W 3645

COMMENTS: Placed yellow bearing tag on Tele Pole number 162.

Brass Cap is ± 2" Below Road Surface.

IN THE PRESENCE OF:

Gale Arthur Roger Kripple
George Urrey

DATE: 4/20/70

PHOTO#:

TITLE GWU

* = County corner tag affixed.