

TILLAMOOK COUNTY REWITNESS

# 380

SECTION COR. SEC. 9/10  
16/15 T 25 R 9 W., WM.

HISTORICAL: GLO T2SR9W Page 9

Book 10 Pg 76	MAPS	MAPS
BK 1 Pg 83	A-1194	B-509
BK 5 Pg 149	A-1209	F-17-5 BK46 Pg
BK 4 Pg 63	B-561	
BK "S3" Pg 78 & 112	A-666 SEE FIELD NOTES	
	A-2037 SEE FIELD NOTES	


CONDITION

FOUND: 2" IRON PIPE x ± 4 FEET LONG

GONE	80" SPR N72°E 163 <sup>IKS</sup>	GLO Pg 9 1857
GONE	4" Willow S43°E 190 <sup>IKS</sup>	GLO Pg 9 1857
GONE	72" SPR N74°E 235 <sup>IKS</sup>	BK10 Pg 76 1890
GONE	6" Willow S51°E 137 <sup>IKS</sup>	BK10 Pg 76 1890
Destroyed -- REFER TO BOOK 3 PAGE 149	1" IRON PIPE SOUTH 20 <sup>00</sup> FT.	BK 1 Pg 83 1949
Destroyed -- REFER TO BOOK 5 page 149	1" IRON PIPE EAST 20 <sup>00</sup> FT.	BK 1 Pg 83 1949
COMMENTS:	FOUND PP# E4-200-15 N49°30'E 24 <sup>95</sup> FT	BK 5 Pg 149 1965
	FOUND PP# S0°30'E 18 <sup>91</sup> FT	BK 5 Pg 149 1965
	FOUND NW COR HSE S38°E 83 <sup>2</sup> FT	BK 5 Pg 149 1965
	FOUND NE COR HSE S47°W 117 <sup>2</sup> FT	BK 5 Pg 149 1965

REWITNESS

1 SET 2" IRON PIPE WITH 3" BRASS CAP IN 10" TILE FILLED WITH CONCRETE  
IN SAME POSITION AS FOUND 2" IRON PIPE feet



NEW ACCESSORY:


COMMENTS: CORNER IS LOCATED IN NORTH DRIVING LANE OF "BURBANK ROAD" AT INTERSECTION OF BRICKYARD ROAD. FLUSH WITH GRAVEL SURFACE (CONC. MON.)

IN THE PRESENCE OF: GALE ARTHUR  
DAN McNUTT

DATE: 3-28-74 PHOTO#:

4/12/74 TITLE

\* = County corner tag affixed.

GWU