

County corner for affixed

TILLAMOOK COUNTY REWITNESS

#403

N. 1/16

COR.

18

T 25

R 9

W., WM.

E. LINE


IN THE PRESENCE OF HISTORICAL:

Book	Page	Year
S3	238	1899
MAP F-41-108		1911
MAP A-421		1950

CONDITION

FOUND: 1/2" Iron Pipe plugged & tacked


COMMENTS:



REWITNESS

1 SET 2" Iron Pipe with 3" Brass Cap in Conc & Tile

W. 15 feet



* 96 " Flat Section

NEW ACCESSORY:

* 40" SPRUCE S08°W 209'5"

* 36" SPRUCE S72°W 60'05"

set flat section in fence line -- corner is ±100' East of G. Coats Camp Rd & ±10' North of a E-W ditch

COMMENTS: A. Duncan proportioned the corner from Stiennon Road monumentation. A. Duncan found an old Iron Pipe at S 1²⁵ and W 9¹⁶ of calculated position and therefore accepted the found 1/2" I.P. W.E. Anderson = C.S. MAP 421 = check distance from section corner by 0.66.

IN THE PRESENCE OF: George W. Uvrey
2"E D.R. Gale Arthur

7/8
1817

DATE: 10/27/69

1" M PHOTO REG

TILLAMOOK COUNTY REWITNESS

TITLE

* = County corner for affixed.