

35	36
2	1

TILLAMOOK COUNTY REWITNESS # 430
 N.W. SEC. 35/36
 COR. 2 T 1 R 10 W., WM.
 S. E.

HISTORICAL: G.L.O. 1510 Pg. 14 SET Post 1857


BOOK PAGE	MAPS
HAYS F 71	F-26
NOTE BIN TILL RIV RD 5	B-555
1 2	B-631

CONDITION	FOUND	4" I.P. WITH PLUG	SEE NOTE BIN TILL. RIV. RD
NOT FOUND	16" SPRUCE	S. 35° E. 45 LKS	G.L.O.
ED. ROTTEN STUMP ^{SCRIBING} _{VISIBLE}	12" SPRUCE	S. 60° W. 49 LKS	G.L.O.
GONE IN SLOUGH	20" SPRUCE	N. 23° E. 75 LKS	G.L.O.
GONE IN SLOUGH	24" SPRUCE	N. 70° W. 116 LKS	G.L.O.

COMMENTS:

REWITNESS

I SET 1 1/2" IRON PIPE WITH 3" BRASS CAP IN 10" TIN CYLINDER FILLED WITH CEMENT AT POSITION OF FOUND 4" IRON PIPE
 60" Hat Section 15 FEET NORTH



NEW ACCESSORY: NO NEW BTS AVAILABLE

W.C.M.C. BEARS	S. 00° 29' 50" W.	195' 10" FEET

COMMENTS: THIS CORNER IS LOCATED @ THE SOUTH TOE OF A DIKE ALONG A SLOUGH IN A SWAMPY AREA.

IN THE PRESENCE OF: DAN McNUTT ALLEN DVORAK

DATE: 7-11-84

PHOTO#: SEE PHOTO # 1108
 LIFTWOOD COMPANY, SEASIDE, CALIF. TITLE

* - County corner tag affixed.