


TILLAMOOK COUNTY REWITNESS #461

SEC. 5

1/4 COR.  $\frac{17}{20}$  T 2S R 10 W., WM.



HISTORICAL: GLO Book Page 19

GLO 1857	17" Spruce N32°E	62 LKS
GLO 1857	30" Spruce S62°W	37 LKS
Rewitness 1939	12" Spruce EAST	6° feet (Refer to Book 62 page 19)
Rewitness 1939	14" Spruce NORTH	10° feet
MAP A-20 by W.E. ANDERSON (MAY 1946)		
MAP A-20 Revision by J.L. CARLICH (MARCH 1969)		
FOUND: F-19-21		

CONDITION


Fair -- Rusting	Iron Bar 1 1/4"	
	Both GLO Bearing Trees are gone	
Good	1939 - 12" Spruce East 6° ft	1971 = NOW 30"
Good	1939 - 14" Spruce North 10° ft	1971 = NOW 18"

COMMENTS: Refer to MAP A-163  
 \* 12" SPR. EAST 6°, 1988 = Now 33"  
 \* 14" SPR. NORTH 10°, 1988 = Now 31"  
 RETAGGED 1988

REWITNESS

Placed cement & tile around corner

1 SET 2" Iron Pipe with Brass Cap marked as sketched  
 feet  
 96 " Hat Section S 70° W 15 feet



NEW ACCESSORY:


COMMENTS: Set 2" Iron Pipe over 1/2" Iron Rod.

Put yellow BT tags on 1939 BT's and "Do Not Cut" on 1939 BT's.  
 Corner is located 161.80' west of center of Whiskey Creek Road. Corner is located ± 30' North of Flisram Road. Corner is between two roots of a Hemlock tree.

IN THE PRESENCE OF:

4-14-88 D1 P  
 12-22-71

Gale Arthur      Gale Arthur  
 George Urrey      Roger Knippel

DATE: 4-1-69

PHOTO#:

TITLE  
 G.W.W.

\* = County corner tag affixed.