


TILLAMOOK COUNTY REWITNESS # 471

SEC. 36 | 31 COR. T 2 S R 10 & 11 W., WM.



HISTORICAL: GLO Pg 5 2511 FD. POST & UNRECORDED 1890  
GLO Pg 73 2510 SET POST 1856

BOOK	PAGE	MARS
3	197	F-27-2


60" CONDITION BADLY RUSTED FOUND, 2" IRON PIPE CEMENT FILLED BK 3 Pg 197

FD STUMP SCRIBING VISIBLE NOW 31.4' TO FACE	60" SPRUCE	S. 62 1/2° W. 53 LKS	GLO Pg 5
GONE	20" HEMLOCK	S. 21 1/2° E. 29 LKS	GLO Pg 5
FD ROTTEN STUB SCRIBING VISIBLE NOW 21.8' TO FACE	30" HEMLOCK	N. 50° E. 45 LKS	GLO Pg 5
NOW 36" STUMP 34.9' TO CHAPPED OUT FACE	24" HEMLOCK	N. 42° W. 56 LKS	GLO Pg 5

COMMENTS:

REWITNESS

I SET 1 1/2" IRON PIPE WITH 3" BRASS CAP IN CONCRETE CYLINDER AT POSITION OF FD. 2" I.P. FILLED WITH CEMENT. \* 60" Hat Section SOUTH 12 FEET



NEW ACCESSORY:

NO NEW TREES AVAILABLE

COMMENTS: THIS CORNER IS LOCATED ± 170 NLY OF CAPE LOOK OUT ROAD ON A STEEP BRUSHY HILLSIDE LAYED FD. MONUMENT ALONGSIDE NEW MONUMENT.

IN THE PRESENCE OF: DAN MCNUTT AL DVORAK

DATE: JULY 1984

PHOTO#:

\* = County corner tag affixed.

TITLE