

TILLAMOOK COUNTY REWITNESS #473  
 SEC. 2/11  
 SECTION COR. 11/12 T 35 R 7 W., WM.

HISTORICAL: GLO Pg. 5 357 1873

BOOK	PAGE	MAPS
2	169	A-706
		B-683


CONDITION GOOD FOUND, O.S.B.F. 1 1/2" I.P. WITH 3" BRASS CAP BK. 2 P. 169

FD. NOW 60" STUMP ON WEST SIDE OF ROAD.	40" FIR	N. 32° W. 42 LKS.	G.L.O. Pg. 5
GONE	15" HEMLOCK	N. 22° E. 69 LKS.	G.L.O. Pg. 5
FD. ROOT REMAINS	16" HEMLOCK	S. 64° E. 118 LKS.	G.L.O. Pg. 5
FD. ROTTEN REMAINS NO <sup>W</sup> <sup>OV</sup> <sup>ER</sup>	18" HEMLOCK	S. 40° W. 57 LKS.	G.L.O. Pg. 5
FD. SCRIBING VISIBLE	51" FIR STUMP	N. 18° 30' E. 49 2'	BK. 2 Pg. 169
FD. NOW STUMP SCRIBING VISIBLE	47" FIR	S. 68° 30' E. 126 5'	BK. 2 Pg. 169
FD. ROTTEN STUMP NO MARKS.	50" FIR SNAG	S. 15° W. 46'	BK. 2 Pg. 169

COMMENTS:

REWITNESS

1 SET 10" CONCRETE CYLINDER AROUND FOUND 1 1/2" IRON PIPE WITH  
 3" OSBF BRASS CAP BK. 2 Pg. 169 1952  
 \* 60" Hat Section SOUTH 12 FEET



NEW ACCESSORY, FD. NEW BTS PROBABLY, BK. M. BTS ± 1978

* 9" FIR	S 15° W. 21 24'	SCRIBING VISIBLE ON PARTIALLY HEAVED
* 14" FIR	N. 50° W. 33 54'	" " "
* 13" FIR	N. 79° E. 21 00'	" " "
* 14" FIR	S. 19° E. 14 63'	" " "

COMMENTS: THIS CORNER IS LOCATED ON THE EAST EDGE OF THE BOUNDARY ROAD @ THE TOP OF A SMALL CUT.  
 FD. TAGS ON OLD ROTTEN STUMP ± S38 W 16' DATED 6-30 & 8-22-56. ALSO FD TAG ON 5" FIR ± 3' WEST DATED 2-1-78.

IN THE PRESENCE OF: DAN McNUTT ALDUARAK

DATE: 5-20-85 PHOTO#:

\* = County corner tag affixed.

TITLE