

TILLAMOOK COUNTY REWITNESS # **485**

SEC. $\frac{2}{11}$ COR. $\frac{1}{4}$ T **35** R **9** W., WM.

HISTORICAL: G.L.O. 359 Pg. 56 1896


Book	PAGE	
1	498	
B.L.M. MICROFILM 359		

CONDITION	FOUND	2" I.P. WITH 3" B.L.M. BRASS CAP	BLM MICROFILM
GONE IN CLEARCUT	10" ALDER	N. 70° W. 20 LKS.	G.L.O. Pg. 56
GONE IN CLEARCUT	10" ALDER	S. 32° W. 20 LKS.	G.L.O. Pg. 56
NOW 54" STUMP IN CLEARCUT	36" SPRUCE	N. 86° W. 111 LKS.	B.L.M. MICROFILM
NOW 46" TREE FAE OVERGROWN	20" CEDAR	S. 48° E 65 LKS.	B.L.M. MICROFILM

COMMENTS:

REWITNESS

1 SET 10" CONCRETE CYLINDER AROUND FOUND B.L.M. 2" IRON PIPE WITH 3" BRASS CAP SEE B.L.M. MICROFILM 359
 * 72" Hat Section WEST 15 FEET



NEW ACCESSORY:

COMMENTS: THIS CORNER IS LOCATED SOUTH OF EAST BEAVER CREEK IN A RECENT CUTTING CORNER. CLEAR CUT NE - NW - AND SW QUADS.

IN THE PRESENCE OF: DAN MCNUTT AL DVORAK

DATE: 3-15-88

PHOTO#: 33-15-1988

Alvin J. ... C.S.
TITLE

County corner tag affixed.