


TILLAMOOK COUNTY REWITNESS

#525



1/4

SEC.

COR.

20121 T 3 S

R 9

W., WM.

HISTORICAL: GLO Pg. 33 359 ^{Now MISSING} SET POST 1880

Book	PAGE	MAPS
3	387	B-511
2	519	B-645

CONDITION GOOD

FOUND; OSBF 1 1/2" I.P. WITH BRASS CAP BK. 2 Pg 519

GONE	40" FIR	S. 32° E. 64 LKS	GLO Pg. 33
GONE	60" SPRUCE	S. 3° W. 59 LKS	GLO Pg. 33
GONE POSITION IN LOGGING RD.	10" SPRUCE	S. 86° W. 66 ³ FT	B2 Pg 519
ED. NOW STUMP 6' HIGH	17" ALDER	N. 18 1/2° E 19 1/2 FT	B2 Pg 519
FD. NOW STUMP 7' HIGH ^{SCRIBING VISIBLE}	18" ALDER	N. 38° W 9 1/2 FT	B3 Pg. 387


COMMENTS:

REWITNESS

1 SET CONCRETE AROUND FOUND OSBF 1 1/2" IRON PIPE WITH BRASS

CAP SEE BK: 2 Pg 519

* 60" Hat Section NORTH 15 FEET



NEW ACCESSORY,

NO NEW B.T.S	AVAILABLE

COMMENTS: THIS CORNER IS LOCATED ± 50' ELY OF A GRAVEL LOGGING ROAD; ON A STEEP SLOPE. AREA HAS BEEN RECENTLY CLEARCUT.

IN THE PRESENCE OF: DAN MCNUTT ALLAN DVORAK

DATE: 9-17-84

PHOTO#:

TITLE

* = County corner tag affixed.