

TILLAMOOK COUNTY REWITNESS #555
 SEC. 30/29 T 35 R 9 W. WM.

HISTORICAL MAPS	MAPS F-17-1	MAPS
B-264 WEA 1886 Spike in Rd	C-332 R.S. 287 Fd 5/8 IR.	A-1540 Iron Rod R.S. 707
A-234 Galvanized Iron Ppc R.S. 150 Yr. 1949	B-591 RES. ENG. K.D. WOLFE Fd 3/4 Bolt head	F-40-40 Spike & Co Rd Hudson 1947
A-330 Spike ENG # 1697	F-40-56 Galvanized Iron Ppc 1912-17 U.S. JACKSON	F-40-191 Hudson 1953
A-238 R.S. 188 RD C Sheppard spike	Book 5 Page 212	F-40-142 W.W. Hudson 1963 ENG # 2747
A-1025 R.S. 287 1962	Book "L29" Page 10	A-1885 R.S. 287 Fd 5/8 Iron Rod 1969
A-823 R.S. 287 Iron Ppc 1989	Book 53 Page 766	A-282 WEA. ENG. # 1697 Yr. 1949 Fd. Mail & RD.


CONDITION	FOUND:	Book #	Page #
O.K.	FLAG POLE distance to CENTER OF POLE 110.10 FEET	5	212
GONE	Power Pole #3 with "A" 58.35 Feet	5*	212
O.K.	Power Pole #L3 with "A" 34.95 Feet	5	212
O.K.	4x4 Post North 15 I	5*	212

COMMENTS:

REWITNESS

1 SET 1/4" IRON REBAR CENTER PUNCHED

"x" "x" " Post N.W. feet
 " Hat Section S. E.



NEW ACCESSORY:

COMMENTS: Placed 1/4" Iron bar over found iron bar.

IN THE PRESENCE OF: Gale Arthur
 ROGAR Knippel

DATE:

COB: PHOTO#: 2EC
 TILLAMOOK COUNTY REWITNESS TITLE

* - County corner tag affixed.