

TILLAMOOK COUNTY REWITNESS #567
 SEC. $\frac{1}{12}$ COR. $\frac{1}{4}$ T 35 R 10 W., WM.

HISTORICAL: G.L.O. 3510 Pg. 15 1882

BOOK	PAGE	MAPS
2	484	A-901
1	54	
4	11	


CONDITION GOOD FOUND, O.S.B.F. $1\frac{1}{2}$ " I.P. WITH 3" BRASS CAP BK. 2 Pg. 484

GONE	10" SPRUCE	S. 24° E. 13 LKS	G.L.O. Pg. 15
GONE, FALLS IN CAT ROAD	8" SPRUCE	N. 34° W. 39 LKS	G.L.O. Pg. 15
FD. NOW STUMP FACE GROWN OVER	39" HEMLOCK	S. 17 $\frac{3}{4}$ ° W. 48 $\frac{1}{2}$ FT.	BK. 2 Pg. 484
FD. NOW 40" STUMP 0' HIGH FACE GROWN OVER	27" SPRUCE	N. 79° E. 26 $\frac{1}{2}$ FT.	BK. 2 Pg. 484

COMMENTS: ALSO FOUND 1" IRON PIPE 2' ELY OF CORNER
 NO RECORD OF ESTABLISHMENT

REWITNESS

I SET 10" CONCRETE CYLINDER AROUND FOUND $1\frac{1}{2}$ " O.S.B.F. IRON PIPE
 WITH 3" BRASS CAP C.S. BOOK 2 PAGE 484.
 * 72" Hat Section SOUTH 1 $\frac{1}{2}$ FEET



NEW ACCESSORY:

* 6" HEMLOCK	S. 33° E. 94 $\frac{1}{2}$ '	1/4 S 12 BT CS
* 8" HEMLOCK	S. 49° W. 92 $\frac{1}{2}$ '	1/4 S 12 BT CS

COMMENTS: THIS CORNER IN A FLAT AREA
 AT THE SW CORNER OF A RECENT CLEAR CUT.
 10' SOUTH OF A 50" DOUBLE SPRUCE STUMP.

IN THE PRESENCE OF: DAN MCNOTT AL DVORAK

DATE: 3-3-88

PHOTO#: 253-14-1988

ALLAN E. DUNN, C.S.

County corner tag affixed.

TITLE