


| | | | | |
|---|--|-------------------|---------------------|----------------------|
| Index File No. E-11 | CORNER RECORD (SEARCH) (Ref. FSM 7151.4) | | Tract or Survey No. | Cor. No. #589 |
| T 35 R. 10W R.D. Hebo | County TILLA. | | | |
| Merid. Will. | N.F. SIUSLAW | State ORE. | | |
| CORNER DIAGRAM | DESCRIBE CORNER MONUMENT FOUND GLO 1933 SET BRASSCAP & MARKED; | | | |
|  | 2.5" HEMLOCK, N. 22° W, 15 LKS. 1.5" HEMLOCK, S. 69° W, 14 LKS. | | | |
| | DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND | | | |
| | FOUND GLO BRASSCAP C-2 ALUM. TAG ON HEM. STUMP 8 FT. SE. | | | |
| PHOTO IDENTIFICATION DATA | DON WOOD, FORESTER 11-26-70 | | | |
| Photo No. EIJ 7-18-6 | | | | |
| Filed At: | | | | |
| Object Ident: | | | | |
| Ident. By: | DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER | | | |
| Signature | FOUND 2 1/2 BRASSCAP SET 1933. | | | |
| PLANE COORDINATE POSITION | FOUND 34" ROTTED HEMLOCK STUMP, N. 22° W, 15 LKS. WITH ILLEGIBLE SCRIBE MARKS. | | | |
| State _____ Zone _____ | FOUND 18" HEM. STUMP S. 75° W, 14 LKS. NO VISIBLE MARKS | | | |
| X _____ | Signature Leonard Whitmore Date 5-6-71 | | | |
| Y _____ | | | | |
| Estab. By _____ Agency _____ | | | | |

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set IRON FENCE POST 1 FT. S.W. OF B.C. ATTACH "BOUNDARY" AND "Penalt" TO DESTROY" SIGNS.

ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

I SCRIBE ONE NEW BT:
18" HEMLOCK, N. 18° W, 12 1/2 FT. SCRIBED "1/4 S 4 BT."
DISTANCE IS TO SIDE CENTER.
VAR. 21°

Leonard Whitmore, Deputy Tillamook County Surveyor, 2-23-1976

Work Done By _____ Title _____ Date _____ State Registration No. or Agency _____

Certified Cor. Record Prepared? Yes No Filed At: _____ Date _____

REMARKS
CORNER IS ON GENTLE SLOPE DOWN TO THE NORTH.
HEAVY SALAL.

T. 35 R. 10W 1/4 Cor. 1/4