


TILLAMOOK COUNTY REWITNESS # 594



SECTION COR. SEC. 718 / 1817 T 3 S R 10 W., WM.


HISTORICAL: GLO set Post Page 47 MAPS
 Book 4 Pages 51 & 77 B-292
 Book 1 Page 89 = Bk 4 Pg 77 F-28-18 1968 FD cor
 Book 5 Page 217
 Book S3 Page 126
 Book X Page 4-5-13 & 25 (FILED IN SEC 18-3510
 NOTE BIN)

CONDITION	FOUND:	1 1/2" Iron Pipe 5 feet long		
Fd 9" Pine Scribing visible	5" Pine N27°W 68 ⁸³	BK 5 Pg 217	1966	
Fd rusted - ok.	2" I.P. S17°W 50 ⁸⁹	BK 5 Pg 217	1966	
Found ^{scribing visible} school marm Pine	10" Pine S34 1/2°W 300 ⁹	Bk 4 Pg 77	1948	
Gone	6" Pine S5°35'E 533 ²	BK 1 Pg 89	1948	
Gone	2" I.P. N51°E. 50 ⁸⁹	BK 5 Pg 217	1966	
Gone	16" Hemlock S20°E. 30 ⁹	Bk 4 Pg 51	1948	

COMMENTS:

REWITNESS

I SET 2" Iron Pipe ^{with Brass Cap} over found 1 1/2" Iron Pipe - set in Concrete and tile feet



96 " Hat Section EAST 145 ft

NEW ACCESSORY:

6" Pine	S75°E	152 ⁷²	
5" Pine	S20°W	56 ⁶⁵	

COMMENTS: Length of Iron Pipe at corner is

± 6 feet, and 8" of pipe is above ground. Corner is located ± 20 feet east of E of Derrick Road. A high dune (± 60) is west of corner & Rd. Rolling dunes EAST of cor.

IN THE PRESENCE OF: George W. Urrey

2 E' Dale Arthur
 COB' Roger Knippel

DATE: 12-24-71

1" PHOTO# SEC'

TILLAMOOK COUNTY BEARERS TITLE

* = County corner tag affixed.