


USDA-FOREST SERVICE R.D. HEBO County TILLA #595
 Index File No. A-3 N.F. SIUSLAW State ORE.

T 3.5 R. 10W DESCRIBE CORNER MONUMENT FOUND GLO 1933 SET BRASS CAP & MKD
 Merid. W.M. 10" Hem, S. 2° E, 32 LKS.
16" Hem, S. 50° W, 23 LKS.

CORNER DIAGRAM:


DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND
FOUND BRASS CAP SET IRON FENCE POST ALONGSIDE.
FOUND 4" X 4" WHITE POST, 1 FT. NW.
THE S.W. BT IS UPROOTED.
THE S.E. BT IS GONE.
TREES ARE TOO SMALL TO SCRIBE.

PHOTO IDENTIFICATION DATA
 Photo No. ETS-5-12 DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER
 Filed At. ETS-5-128 CORNER IS 150 FT. W. OF SPUR ROAD,
 Object Ident. 154 FT. E. IS SPUR RUNNING N.E.

Ident. By Leonard Whitmore Signature Leonard Whitmore Title Forestry Tech Division Timber Headquarter Hebo
 Date 3-3-76

PLANE COORDINATE POSITION
 State _____ Zone _____
 X _____

COMMENTS:

REWITNESS

I SET _____
 _____ Post N.W. _____ feet
 _____ Hat Section S. E.

NEW ACCESSORY:

COMMENTS:

IN THE PRESENCE OF: _____

DATE: _____ PHOTO # _____ TITLE _____

* = County corner tag affixed.