

19 20  
30 29

TILLAMOOK COUNTY REWITNESS #626

N.W. 1/4 SEC. 29 T 35 R 10 W., WM.


HISTORICAL: GLO Page 43 (1882)  
 Book 10 Page 58  
 Book 53 Page 448 MAP F-40-58  
 MAP C-36  
 MAP B-344 Refer to field notes (Brightwaters Road Sec 30 T35R10W)  
 Field notes Sec 20 T35R10W CLAY MYERS

CONDITION fair FOUND: 1 1/2" Iron Pipe in tide flats by using  
map B-344 & field notes.

COMMENTS:

REWITNESS

1 SET 2" Iron Pipe with 3" Brass Cap over found 1 1/2" Iron  
Pipe. I placed 10" Tile around the 2" Iron  
Pipe and filled the tile with concrete.



NEW ACCESSORY:  
96" Hat Section EAST 2 25  
96" Hat Section South 2 39

COMMENTS: CHECK YOUR TIDE TABLES  
BEFORE PROCEEDING -- OR WEAR HIP BOOKS

IN THE PRESENCE OF: Geo W Ulrey Al Duncan  
Gale Arthur Roger Knipple

DATE: 5-26-72 PHOTO#: \_\_\_\_\_ TITLE \_\_\_\_\_

\* = County corner tag affixed.