

CORNER RECORD (SEARCH)
(Ref. FSM 7151.4)

Tract or Survey No. T-9
Cor. No. #707

File No. 45 R. 9W R.D. Hebo County TILLA
Merid. WILL N.F. SIUSLAW State ORE

CORNER DIAGRAM

DESCRIBE CORNER MONUMENT FOUND
GLO 1878 SET POST + MKD:
72" SNA9, S. 40° E, 29 LKS.
20" SNA9, S. 11° W, 31 LKS.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND
POST IS GONE.
I FOUND 27" SNA9, S. 7° W, 31 LKS. WITH FAINT SCRIBE
MKS. "1/4".
FOUND ROTTED STUMP OF A SNA9, S. 43° E, 29 LKS. WITH
MARKS ROTTED OFF.

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER
I SET 4X4X24 HARD LIMB AT COR. POINT MKD. 1/4 ON
WEST SIDE FROM WHICH I MKD:
A 20" FIR, N. 20° E, 35 FT. 1/4 S 28 BT CS.
A 15" FIR, N. 74° W, 46 FT. 1/4 S 29 BT CS.
PAINT RED BAND & PUT BT SIGNS ON TREES.

PHOTO IDENTIFICATION DATA
Photo No. E13-9-138
Filed At. _____
Object Ident. _____
Ident. By _____
Signature _____

PLANE COORDINATE POSITION DATA
State _____ Zone _____
X _____
Y _____
Estab. By _____ Agency _____

Signature Leonard Whitmore Title Forestry Tech Division Tilla Headquarters Hebo Date 5-8-69 7100-52 (3/68)

REWITNESS

I SET _____ "x" "x" " Post N.W. ... feet
" Hat Section S. E.

NEW ACCESSORY:

COMMENTS:

NOTE
L. WHITMORE IS
A DEPUTY CO. SURV.
FOR POSITIVE OLD
MONUMENT FOUND
RE-WITNESSING

IN THE PRESENCE OF:

DATE: _____ PHOTO # _____ REC # _____
TITLE _____

* - County corner tax affixed