

29
32

TILLAMOOK COUNTY REWITNESS #784

N. 32 SEC. 29
COR. 32 T. 4 S R. 10 W., WM.
S. 29

HISTORICAL: GLO Pg. 42 SET Post ± 1879

BOOK	PAGE	
51	63	
53	80-81	
53	190	


MISC. SEC. FILE SEC 29.4510

CONDITION	FOUND: NOTHING AT CORNER POSITION		
FD ROTTEN STUMP ^{OLD ARE} MARKS	20" SPRUCE	S. 70° E. 75 LKS	GLO. Pg. 42
NOT FOUND	4" MAPLE	N. 30° W. 27 LKS	GLO. Pg. 42

COMMENTS:

REWITNESS

1 SET 1/2" IRON PIPE WITH 3" BRASS CAP IN 10" TILE &
CEMENT FROM FD GLO BEARING TREE
* 86" Hat Section WEST 15 FEET



NEW ACCESSORY:

* 18" ALDER	N. 28° W. 17.69'	1/4 S 29 BT CS
* 20" ALDER	S. 46° E. 63.50'	1/4 S 32 BT CS

COMMENTS: THIS CORNER IS LOCATED ± 1200 FT
WLY OF RESORT DRIVE ROAD IN A GROVE OF ALDERS.
ACCORDING TO WAYNE COOK PLS 1098 THIS POSITION FITS
REASONABLY TO PROPORTION POSITION. A SUBSEQUENT TRAVERSE OF
THE ROAD SHOWS THIS POSITION
GRAPHICALLY FITS "BILLY" ANDERSON'S
POSITION IN FIELD NOTE BOOK # 51 PAGE 63
SEE SEC MISC. FILE FOR TRAVERSE & FIELD
NOTES to substantiate this positioning. PHOTO #:
DATE: 6-6-79

GALE ARTHUR DAN MCNUIT

* = County corner tag affixed.

TITLE