



TILLAMOOK COUNTY REWITNESS #810

Common COR. SEC. 5 4511 4510 13 18 24 19 T 4 S R 10 11 W., WM.

HISTORICAL:

A-1391	B-331	F-5-4
A-1536	B-407	
A-1853	C-174	
"GLO BOOK" 4510	Page 7	
"GLO BOOK" 4511	Page 4	

CONDITION	FOUND: a moving sand dune
	Fd 1 1/4" Iron Pipe 2-3-72

COMMENTS: THIS CORNER WAS DUG UP AND RESET BY FORREST SERVICE SEE CS MAP #B-1282

2-3-72 REWITNESS

Replaced Found pipe with Brass Cap & 2" Iron Pipe in Concrete & tile

1 SET 1 1/2" Iron pipe 7 feet long and placed it ± 16" above ground

4" x 4" x 98" Post Near Corner

96" Hat Section is ± 1 1/2 feet EAST, GONE 12-88

RESET NEW 84" HAT SECTION 125 FEET EAST.

NEW ACCESSORY: NO BT'S AVAILABLE IN AREA

1" Iron Pipe 4 1/2 feet long	EAST 5°	Plug & nail	THIS POSITION DIFFERENT SEE B-1282
1 1/2" Iron Pipe 3° feet long	South 5°	Plug & nail	THIS POSITION DESTROYED

1 1/2" IRON PIPE FOUND HORIZONTAL, LAYING AT FOOT OF SAND DUNE, I RESET 5° NORTH D1 P 12-88

COMMENTS: This corner was set by transit and tape, from the information and ties shown on the county Surveyor's maps -- B-407 and C-174 --. The corner is west of a North-South planting line of beach grass and ± 3 feet North of top of a E-W Sand dune.

IN THE PRESENCE OF: A Duncan 793
G. Arthur
S Skinner

DATE: 1967 PHOTO#: 280

County corner tag affixed. TITVWOCK CORNER TAG #112 TITLE GWA

