

5	4
8	9

TILLAMOC COUNTY REWITNESS #863
 N.W. 9 COR. SEC. 514 T 5S R 10 W. WM.
 S. E. 5

HISTORICAL: GLO Pg. 54

Book	Page	MAPS
S3	24	B-32
S3	246	B-602
5	160	

CONDITION	FOUND:
FO 2" IP WITH BC GOOD	2" IRON PIPE WITH BRASS CAP BK 5 Pg 160
FO 2" IP WITH BC GOOD	REFERENCE MON N 42° 30' W 232' BK 5 Pg 160
	" " N 48° 30' E 212' BK 5 Pg 160

THESE WERE DESTROYED IN DIVING OPERATION PRIOR TO THEIR DESTRUCTION. M'NUTT TIED OFF THE CORNER & AFTER CONSTRUCTION RE-SET THE CORNER FROM HIS TIES & MADE NEW REF. MONS LISTED ON PAGE 2

COMMENTS:

REWITNESS 1 OF 2

I SET CONCRETE AROUND FOUND 2" IRON PIPE WITH BRASS CAP
 SET BY RS 608
 84" Hat Section SOUTH 12 FEET

T55 R10 W
 55 / 54
 58 / 53
 1971
 RS 608

NEW ACCESSORY:

COMMENTS: THIS CORNER IS LOCATED 500' EAST OF A SLOUGH 60' WIDE AND 10' NORTH OF THE TOE OF THE DIKE ON THE SOUTH SIDE OF THE LITTLE NESTUCCA RIVER.

IN THE PRESENCE OF: GALE ARTHUR DAN M'NUTT

DATE: 2-75
 PHOTO: [Signature] C.S.
 COUNTY CORNER TAG AFFIXED

TILLAMOC COUNTY REWITNESS

<table border="1" style="width: 100%; height: 100%; border-collapse: collapse;"> <tr><td style="width: 50%; height: 50%;"></td><td style="width: 50%; height: 50%;"></td></tr> <tr><td style="width: 50%; height: 50%;"></td><td style="width: 50%; height: 50%;"></td></tr> </table>					<p>N.W. COR. SEC. _____ T _____ R _____ W., WM.</p> <p>S. E. COR. DLC.# _____</p> <p>HISTORICAL:</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <tr><td style="width: 50%; height: 20px;"></td><td style="width: 50%; height: 20px;"></td></tr> <tr><td style="width: 50%; height: 20px;"></td><td style="width: 50%; height: 20px;"></td></tr> <tr><td style="width: 50%; height: 20px;"></td><td style="width: 50%; height: 20px;"></td></tr> <tr><td style="width: 50%; height: 20px;"></td><td style="width: 50%; height: 20px;"></td></tr> </table>																				
<p>CONDITION</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <tr><td style="width: 33%; height: 20px;"></td><td style="width: 33%; height: 20px;"></td><td style="width: 33%; height: 20px;"></td></tr> <tr><td style="width: 33%; height: 20px;"></td><td style="width: 33%; height: 20px;"></td><td style="width: 33%; height: 20px;"></td></tr> <tr><td style="width: 33%; height: 20px;"></td><td style="width: 33%; height: 20px;"></td><td style="width: 33%; height: 20px;"></td></tr> <tr><td style="width: 33%; height: 20px;"></td><td style="width: 33%; height: 20px;"></td><td style="width: 33%; height: 20px;"></td></tr> </table>													<p>FOUND:</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <tr><td style="width: 33%; height: 20px;"></td><td style="width: 33%; height: 20px;"></td><td style="width: 33%; height: 20px;"></td></tr> <tr><td style="width: 33%; height: 20px;"></td><td style="width: 33%; height: 20px;"></td><td style="width: 33%; height: 20px;"></td></tr> <tr><td style="width: 33%; height: 20px;"></td><td style="width: 33%; height: 20px;"></td><td style="width: 33%; height: 20px;"></td></tr> <tr><td style="width: 33%; height: 20px;"></td><td style="width: 33%; height: 20px;"></td><td style="width: 33%; height: 20px;"></td></tr> </table>												
<p>COMMENTS:</p>																									

REWITNESS 2 OF 2

I SET 2" IRON PIPE W 3" BRASS CAP FROM RMS I RESET IN THE FIELD
SOUTH OF THE DIKE
84" Hat Section SOUTH 10 FT.

T5SR10

S5	S4
S8	S9

RS-287

1976

NEW ACCESSORY:

COMMENTS: THIS CORNER AND RMS WERE REMOVED
AND LATER RESET DUE TO CONSTRUCTION ON DIKE. ALSO SEE FIELD NOTES
T5SR10W AND RE/WIT. CARD #1


IN THE PRESENCE OF: DAN MCNUTT GALE ARTHUR

DATE: 10-76 PHOTO# TITLE

* = County corner tag affixed.

TSSRION 8-2-76
 01 01
 14 43

SEC COR
 121717
 121717
 121717



FLY THE
 SEC COR

SET STEEL FENCE
 POST 10 NORTH
 OF RMS

1/4 8 1/2 10W

I REMOVED RMS
 FROM DICE AND
 SET IN FIELD

SE RM

618 1/2

FILTY
 SW RM

4) 222.45
 2) 97.50

SE RM

618 1/2

SEC COR	2" IP WITH BC			
SW RM	2" IP WITH BC			
SEC COR	2" IP WITH BC			
1) RM	161 71 @ LEVEL			
4) RM	51 35 2 + 1			
2) RM	308 24 9			
M) RM	308 24 85	128 24 85 RTA		
SEC COR	2" IP WITH BC			
4) RM	105 08 5			
2) RM	254 51 6			
M) RM	254 51 55	74 51 55		