

13 | 14
20 | 19

C.W.E. 1/64 COR.

SEC.

7

T 5 S

R 10

W., WM.

HISTORICAL: G.L.O. Pg 35 259 SET STONE 12"x9"x6" 1872

CONDITION BROKEN

FOUND; 12"x9"x6" (ORIGINAL) STONE MARKED X X 11

G.L.O. Pg 32 259

BROKEN X X 11

COMMENTS:

REWITNESS

1 SET 1 1/2" IRON PIPE WITH 3" BRASS CAP IN 10" CONCRETE CYLINDER

POSITION OF FOUND ORIGINAL 12"x9"x6" STONE MARKED X X 11

60" Hat Section EAST 15 FEET

ONLY AND PART OF ANOTHER WAS BROKEN OFF

GVT LOTS

13 | 14
20 | 19

LS 793

1985

NEW ACCESSORY:

NO NEW B.T.S AVAILABLE

COMMENTS: THIS CORNER IS LOCATED IN AN E-W FENCE LINE ± 750' EAST OF HWY 101. LAYED FOUND STONE ALONGSIDE MONUMENT.

IN THE PRESENCE OF: DAN McNUTT AL DVORAK

DATE: 4-16-85

PHOTO#:

TITLE

* = County corner tag affixed.