

T5S R11W	T5S R10W
12	7
13	18

TILLAMOOK COUNTY REWITNESS

#886

SECTION COR. ~~12~~ 13 | ~~7~~ 18 T 5S R 10 W., WM.

HISTORICAL: GLO. 5S11W PAGE 3
GLO. 5S10W PAGE 49 J.W. MELDRUM 1872


O.S.H.D. F-14-20 1924

O.S.H.D. F-27-14 1965

B-902

CONDITION	FOUND:
Good	3/4" Iron Pipe - Plugged & Tacked by STONE IV

COMMENTS: Corner markers located at fence intersection



REWITNESS

Set in CONC & Tile

1 SET 2" Iron Pipe with 3" Brass Cap set over 3/4" Iron Pipe

"x" "x" "Post" ~~12~~ 15 feet

90" Hat Section ~~12~~ E.

T5S

R11W	R10W
12	7
13	18

RS287

1970

NEW ACCESSORY:	(ALL DIST: TO FACE) scribed
*8" Triple Alder	N07°E 68 ²⁸ 57 BT CS
*32" Spruce	N22°E 68 ⁴⁵ 57 BT CS 5S10
*12" Alder	N70°E 65 ⁸⁰ 57 BT CS

COMMENTS: Corner is in open field. A small gully runs Northwesterly from corner. Gully slopes downward

IN THE PRESENCE OF: George Urrey
Gale Arthur

DATE: 8-12-70

PHOTO#: REC

TILLAMOOK COUNTY SURVEYOR TITLE
G.W.U.

County corner tag affixed.