

TILLAMOOK COUNTY REWITNESS #889

~~N.W.~~ SEC. COR. 8-9-17-16 T 5 S R 10 W., WM.  
S.E. DIC.#

HISTORICAL: GLO 10x10x15 Stone  
Hay's 16x12x12 Stone Book F Page 58


CONDITION	FOUND:
Good	Stone With X marked on it, Broken off of original Stone.
Good	26"± Spruce S58E 150 Marked with X

THE MAIN PORTION OF THE STONE WAS UNDISTURBED. YET THE TOP WAS MISSING. VISIBLE SCRIBE MARKS-- "CS"-- COULD BE SEEN ON THE MAIN STONE. THE TOP PART OF THE STONE MARKED "X" WAS FOUND LYING ALONGSIDE THE MAIN STONE. GWU

COMMENTS:

REWITNESS

I SET 2" Iron Pipe With 3" Brass Cap Set in concrete  
"x" "x" " Post N.W. feet  
84" Hat Section S. EAST 15



NEW ACCESSORY:

30" spruce N86E	27 35	
± 26" spruce S58E	150	Marked with X

COMMENTS: Corner is located in North-South fence line. An also fence line running East from corner is located on slope of open pasture land which runs south ± 500'± feet to small creek.

IN THE PRESENCE OF: Geo Urey  
Gale Arthur  
Dan McNUTT

DATE: 11-73 PHOTO#:

\* = County corner tag affixed.

TITLE