

TILLAMOOK COUNTY REWITNESS #936

N. 1010 SEC. 24
 1/4 COR. 25 T 55 R 11 W., WM.
 S.

HISTORICAL MAPS	MAPS	Book	Page
A-1113	C-351	5	115
A-1186	C-131	HAYS "F"	54
B-507	C-212	GLO	19
C-55	B-589	F-27-27 (MAP)	
C-83	A-1602	F-27-14	
	C-321		

ALSO INITIAL POINT OF MAPS AND LANDS
 CONDITION Good


FOUND: 2" Iron Pipe set by book 5 page 115

* Found 6" Spr N67°W 45 ³¹	in good condition	as reported in Book 5 page 115
* Found 12" Spr S61°E 168 ⁸²	in good condition	as reported in Book 5 page 115

COMMENTS:

REWITNESS

I SET 2" Iron Pipe with 3" Brass Cap in 10" Tile with concrete in place of the found 2" Iron Pipe.
 " Hat Section



NEW ACCESSORY:

COMMENTS:

IN THE PRESENCE OF: Gale Arthur

Jim Boehm
 GWU

DATE: 7-24-72

PHOTO#: 250

* - County corner tag affixed.

TILLAMOOK COUNTY REWITNESS TITLE