## County Surveyor's Record, Tillamook County, Oregon

CHAINS # 1972 95 C#C0+SeC25 5511 Fd 12 1P Plugged and Tack. We Wittness con Then Put A 2" 1.P. over The 1/2" I.P. And Yoused IT ground. IT 770w 13 = 6" Above ground. cor 15 on a Angle. This is All we done. JLC said to do 720 mone. THU IS A HITTORICAL CORNER. AND IS NOT MECESSACILLY AT THE LEGAL CH POSTION AT LEAST THUS PERPETURIES IT A FEW WIEL YEARS. 9HL Captin Co Smary 46