December 22, 1981

CHANS

WITNESSED BY:

- R. Hemmer
- L. Boge
- A. \$lack
- L. Hettema

Nº SECTION 6 (ONLY)

ESTABLISHMENT:

Set 5/8"x30" iron rod with aluminum cap marked "OREGON STATE PARKS."

Set steel post with plain white paddle 2.0' north of iron rod.

12" hemlock S27°E, 25.8' to center, scribed "4S6BT RS691."
13" hemlock S80°W, 17.8' to center, scribed "4S6BT" and attached yellow Parks corner tag.

A 3/4" iron rod bears S89°57'46"W, a distance of 92.60' with a 4"x4" white post marked "USBM" on south side, "N2S6" on east side, 'T3N R1OW" on west side, a distance of 0.5' west of the 3/4" iron rbd. No BT's in evidence.

WITNESSED BY:

- R. Hemmer
- Boge
- S. Doak
- M. Swan

31 T4N

CC 6 5 T3N

ORIGINAL: 1893

At point of intersection is a 30" hemlock (new a 32" stump), scribed "CCT 3N R10W" on south side, "S5" on east side and "S6" on west side, with 5 notches on east and 1 notch on west side for closing corner to Sections 5 and 6, from which a:

30' hemlock bears \$77°E, 48 links (now a 34" stump), marked "T3N R10W \$5BT." 28' hemlock bears \$6'2°W, 59 links (now a 36" downed notten hemlock), marked "T3N R10W \$6BT."

20" hemlock bears N51°E, 33 links, marked "T3N R10W CCS5&6BT."

STATE PARKS CREW FOUND:

A 32" hemlock stump, 5.0' high, rotten, no scribes visible. Found one notch in good wood on west side.

A 36° downed and rotted hemlock 86°_{2} °W, 41.0° , no scribes visible. A 34° hemlock stump, rotted, 2.0° high, 877° E, 31.0° to center, with partial scribes visible "T3N R10W."

STATE PARKS CREW SET:

A \$/8"x30" iron rod with an aluminum cap marked "OREGON STATE PARKS" on the actual township line which is 1.64' south of the center of CC stump.

Set steel post with plain white paddle 2.0' south of iron rod.

7" hemlock \$37°W, 20.0' to center from CC stump, scribed "S6BT" and ttached yellow Parks corner tag.

12 hemlock S25°E, 16.2' to center from CC stump, scribed "S5BT RS691.

WITNESSED BY:

- Hemmer R.
- Boge
- Doak
- M. Swan