OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT Tillamook County Surveyor's Office

SECTION: SE Cor. 4	TOWNSHIP 1 South	RANGE 9 West		
COUNTY: Tillamook		1	DATE: 11-25-11	
CORNER DESIGNATION: The Section Corner common to 3, 4, 9 and				(Please check one)
T. 1 S., R. 9 W., W.M.			×	Condition Report Only
				Restoration
				Rewitness
			므	Unrecorded
				Reset at surface
				Referenced Out
Previous Rewitnesses, Restorations and Surveys, etc: BLM Field Notes Volume: OR-R0377 Pages 104-105, (GLO Book 1S9 Pages 37-38) (1893), Rewitness Book 1 Page 319 (1958), BLM Field Notes Volume: OR-R0575 Page 228, same as				
Rewitness Book 3 Page 150 (1959), Map B-672 (1974), Tillamook County Survey Records.				
Found Monument(s) and Accessories (Condition & Source): This position was determined from original bearing trees and remonumented by Richard A. Morris in 1958. Found 3" dia. O.S.B.F. Brass Cap, up 0.5". The monument is stamped as shown hereon. Found a white painted Cedar post Northwesterly 1.4" from monument. (GLO) – Did not find the (12" Alder bears N 43°30' E 63 lks. [41.58")). (GLO) – Found Hemlock stub, 7' tall, was (12" Hemlock bears S 64°30' E 6 lks. [3.96"]), scribing visible. (GLO) – Found Hemlock stub, 2' tall, was (12" Hemlock bears S 24° W 21 lks. [13.86"]) scribe marks visible. (GLO) – Did not find the (10" Hemlock bears N 30° W 85 lks. [56.10"]). (Book 1, Page 319) – Did not find the (35" Hemlock bears N 27° W 44.2"). (Book 3, Page 150) – Found 40" Hemlock, was (26" Hemlock bears N 86 1/2° E 9.2"), healed face. (Book 3, Page 150) – Found 55" Hemlock, was (39" Hemlock bears N 62° W 108 lks. [71.28"]). () Indicates record information, Tillamook County Survey Records. [] Indicates record links converted to feet. Monument Set (Procedures and Description): N/A Sketch of Found Monument:				
New Accessories set: N/A				
New Bearing Trees Marked: N/A				
Location & Comments: N/A				
Firm / Agency Address: TILLAMOOK COUNTY SURVEYOR'S OFFICE 201 Laurel Avenue Tillamook, Oregon 97141 Party Chief: Joe Jensen, P.L.S. 60067, Deputy County Surveyor Notes: No digital images were taken of the monument or accessories.				REGISTERED PROFESSIONAL LAND SURVEYOR
JANUARY JOSEPH \				OREGON JANUARY 10, 2006 JOSEPH V. JENSEN 60867



RENEWAL DATE: 08-30- 2013