F-40-198
Subdivision of
Section 32, T2N, R10W
Section 5, T1N, R10W
for
Publishers Paper Co.
Scale 1" = 400'
Bearings from Observation
on Polaris at Elongation
± 1953?
P.L. Thompson
Found Axle, A steel Axle. Original Cedar BT N45°E 20 Scribe Marks Visible
N89°37'W 2637
Set E1/16 1318.5 a 1 1/2" x 17" GI Pipe. Metal Tag on 7' Sp. St. S15°E 20. Yew Hub in pipe
Trespass: 2 Spruce 3 Hemlock 24,000 B.M.
Found. Set a Stake N30°E 32 From S32 BT N48°W 22 From S33 BT Scribed 5" H S28 E N89°W 45
N0°20'E
N0°09'E 5269
Not found Not set.
5268
Set Yew hub in 1 1/2" x 17" G.I. Pipe South of logging road. Metal tag on 6' Cedar stump
N.E. Cor Rockaway Beach
Shangle Trespass: 24 Acres. 5 Spruce 3 Cedar 70 Hemlock 89,700 B.M.
MATCH LINE?
M.C. Not found Position Comp. N85°23'W 25 Ch from Spike at N. Bdy Elm
1/4 S Not found. Set 1 1/2" x 3' GI Pipe by Prop. F.S. Metal tag on
S89°40'E
2293
35 Ch
1302
Set E1/16 1/2" x 3' Pipe Scribed 10" Hem E1/16 S20°05'W 14
68
1302
20.0 Ch.
Found. Set 1 3/4" x 42" Axle N75°E 15 from 5' Cedar Stump
S45°E 11 from 2' Hem St and S30°W 17 from 12" Hem St with face and scribe Marks plainly visible. Bearing and dist to this BT Transposed in original Notes with S.E. BT scribed 2 C S4 P S50°E 80
Shangle Trespass: 2 Acres 9 Spruce 64 Hemlock 88,450 B.M.
S0°02'E
1320
N0°06'E
S60°52'W
S.P. Q
100'
1304
Set 1 1/2" x 3' N89°57'W G.I. Pipe Scribed 12" Hem N1/16 E S45°E 2
Set 1 1/2" x 3' GI Pipe Scribed 16" Hem Hub NE 1/4 E N35°E 9
Shangle Trespass: 2 Spruce 1 Cedar 4 Hemlock 47,230 B.M.
Set 1/2" x 3' Pipe For Property Cor. Metal tag on Power pole.
S89°57'E 2221
Shangle Trespass: 1 Cedar 3 Hemlock 4600 B.M.
Set 1/2" x 3' pipe Scribed 6" Hem P.P. Co. E South 19
880
440
2611
N89°5'E 2635
Not found Not set
N89°35'E 2327
Set 1 1/2" x 3' pipe for Property Cor. Metal tag on Str. Sign Post.
Not set
S0°00'W
880
N0°17'E
5204
2605
2293
Set 1 1/2" x 3' GI Pipe Metal tag on Sp. St. 4 South.
See Co Records for found original
2630
1021
1327
Set 1 1/2" x 3' GI Pipe for W 1/16 Metal tag S15°W 11 1310
Set 1 1/2" x 3' GI Pipe for 1/4 S F.S. Metal tag on 6" Hem S30°W 29
2621
5243
1310
N89°18'E
See Book 10 page 138 for these BTs
Found 4" Cedar Post S10°W 13 From 20" Hem With face but No scribe Mks N70°W 6 from rotted Hem. stump, Cruiser Marks.