

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One quarter corner common to Sections 25 and 26,
Township 3 North, Range 6 West, W.M., Tillamook
County, Oregon

ORIGINAL

37.50 chains - ridge top now in place.
39.75 chains - military trail now lost.
40.0 Post, now missing (a one inch rusted iron pipe now
in place) from which a:

28" Cedar bears $N81\frac{1}{2}^{\circ}E$ 86 lks.; now 34" stump, scrib-
ing burnt out of original face.

12" Hemlock bears $N71\frac{1}{2}^{\circ}W$ 12 lks.; now root hole, pieces
of Hemlock roots found.

1/4 Corner point bears East 43 lks.: from which a:

28" Cedar bears $N72\frac{1}{2}^{\circ}E$ 45 lks.; same Cedar as above.

12" Hemlock bears $N33\frac{1}{2}^{\circ}W$ 20 lks.; now 18" rotted
and broken up log, large roots in place.

40.50 chains - a 6' Fir line tree; now 6' stump in
place, original hack marks on N & S sides.

RESTORED

Set $1\frac{1}{2}$ " x 36" galvanized iron pipe with 3" bronze cap marked
"OREGON STATE BOARD OF FORESTRY 1/4 S25 S26 1954 RE 2311,"
34 inches in ground, over top of above 1" rusted pipe, in
mound of stone, and from which a:

12" Fir bears $S57\frac{1}{2}^{\circ}W$ 13.0 ft.; scribed 1/4 S26 BT RE 2311.

9" Fir bears $N55\frac{1}{2}^{\circ}E$ 24.7 ft.; scribed 1/4 S25 BT.

Oregon State Board of Forestry metal location poster on 9"
Noble Fir $N81\frac{1}{2}^{\circ}E$ 28 ft.

Also poster on 12" Fir BT.

Also 4" x $2\frac{1}{2}$ " x 796" white Cedar post 1.5 ft. NW of pipe.

Dated August 25, 1954.

Restored by *Arnold G. Gibson* under my direction.
Arnold G. Gibson, Asst. Engr.



Present and witnessed by Richard Morris, Lloyd Geraths, and
Robert Schumacher.