

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One quarter corner common to Sections 14 and 23,  
Township 1 North, Range 7 West, W.M., Tilla-  
mook County, Oregon.

ORIGINAL

Post, now missing, rotted point of stake set by me in  
1940 found in place, from which a:

- 14" Hemlock bears N18°E 42 lks.; now missing, roots  
in place, good bearing tree when seen by me in  
1939.
- 9" Hemlock bears S16°E 32 lks.; now missing, roots  
in place, good bearing tree when seen by me in  
1939.

RESTORED

Set 1½" x 36" galvanized iron pipe with 3" bronze cap  
marked "OREGON STATE BOARD OF FORESTRY 1/4 S14 S23  
1954 RS 82," 34 inches in ground, in mound of stone,  
and from which a:

- 47" Fir stump bears N55°E 21.1 ft.; scribed 1/4 S14  
BT RS 82.
- 67" Cedar stump bears S19°W 50.2 ft.; scribed 1/4  
S23 BT.


Oregon State Board of Forestry metal location poster on  
67" Cedar stump BT.  
3" x 4" x 72" white Cedar post 1 ft. SW of pipe.

Dated March 31, 1954.

Restored by:



*D. E. Bosworth*



Present and witnessed by: Richard Morris  
Lloyd Geraths  
Alan Ramage  
Robert Cowan