

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to Sections 28, 29 32 and 33,
Township 3 North, Range 6 West, W.M., Tillamook
and Washington Counties, Oregon.

ORIGINAL

Post, now missing, from which a:

- 20" Hemlock bears S77 $\frac{1}{2}$ °W 62 lks.; now missing,
point falls in middle of beaver pond.
- 48" Fir bears N24°40'W 66.5 lks.; now 42" stump,
scribes T3N R6W BT visible.
- 20" Hemlock bears N15°E 72.5 lks.; now missing,
point falls in old skid road.
- 18" Hemlock bears S74°E 7.5 lks.; now just rotted
roots in place.

RESTORED

Set 1 $\frac{1}{2}$ " x 36" galvanized iron pipe with 3" bronze cap marked
"OREGON STATE BOARD OF FORESTRY T3N R6W S29 S28 S32 S33
1954 RE 2311," 33 inches in ground, in mound of stone
3' x 2" x 8", and from which a:

- 6" Fir bears N2°E 39.5 ft.; scribed T3N R6W S28
BT RE 2311.
- 5" Fir bears N86 $\frac{1}{2}$ °W 50.4 ft.; scribed T3N R6W
S29 BT.
- 12" Fir bears S72°W 76.9 ft.; scribed T3N R6W
S32 BT.
- 6" Fir bears S6°E 56.7 ft.; scribed T3N R6W
S33 BT.

Oregon State Board of Forestry metal location poster on 5"
Fir BT.

C-Z poster on original 48" Fir BT.
3 link Cr. 7 ft. North of pipe, course SW.

Dated March 19, 1954

Restored by Richard Morris under my direction.
Richard Morris, Compassman



Present and witnessed by Robert Cowan
Lloyd Geraths

Book I