

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One quarter corner common to Sections 14 and 15,  
Township 1 South, Range 7 West, W.M.,  
Tillamook County, Oregon.

ORIGINAL

Post, now missing, from which a:

- 32" Hemlock bears S70°E 5 lks.; now 42" stub  
40 ft. high, portion of 1/4 scribes visible.
- 28" Hemlock bears N57°W 26 lks.; now 28"  
stub 30 ft. high, face burnt out.

RESTORED

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap  
marked "OREGON STATE BOARD OF FORESTRY 1/4 S15 S14  
1954 RE 2311," 33 inches in ground, in mound of stone,  
and from which a:

- 3" Fir bears S77 1/2°W 117.8 ft.; scribed X
- 48" Fir snag bears S12°E 42.9 ft.; scribed  
1/4 S14 BT RE 2311


Oregon State Board of Forestry metal location poster on  
original 32" Hemlock BT.

Also poster on 48" Fir snag BT.

4" x 4" x 72" white Cedar post 1 ft. NW of pipe.

Dated April 1, 1954.

Restored by Richard Morris under my direction.  
Richard Morris, Compassman



Present and witnessed by Robert Cowan  
Alan Ramage