

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to Sections 14, 15, 22, 23,
Township 1 South, Range 7 West, W.M., Tillamook
County, Oregon

ORIGINAL

Post, now missing, from which a:

- 7" Hemlock bears S77°W 47 lks.; now 17", down and out of place, scribes S R7W visible, root hole in place.
- 5" Vine Maple bears N30°W 20 lks.; now missing.
- 24" Hemlock bears N76°E 68 lks.; now 26" stub 6 ft. high, scribes TLS R7W BT visible.
- 36" Fir bears S53½°E 74 lks.; now 44" snag, scribes R7W visible, rest unexposed.

RESTORED

Set 1½" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY TLS R7W S15 S14 S22 S23 1954 RE 2311," 33 inches in ground, in mound of stone 4' x 3' x 10", and from which a:

- 3" Fir bears N31°W 53.4 ft.; scribed X
- 55" Fir snag bears N84°E 46.4 ft.; scribed TLS R7W S14 BT.
- 67" Fir stump bears S9°W 12.2 ft.; scribed TLS R7W S22 BT RE 2311.
- 82" Fir stump bears S16°E 70.0 ft.; scribed TLS R7W S23 BT.

Oregon State Board of Forestry metal location poster on 55" Fir snag BT.

4" x 4" x 60" white Cedar post 1 ft. NE of pipe.

Dated March 23, 1954.

Restored by Richard Morris under my direction.
Richard Morris, Compassman



Present and witnessed by Lloyd Geraths and Robert Cowan