

124
124

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to Sections 8, 9, 16 and 17,
Township 3 North, Range 7 West, W.M.,
Tillamook County, Oregon.

ORIGINAL

Post, now missing, from which a:

- 6" Hemlock bears N24°E 18 lks.; now 12", down, roots in place, upper face burnt out, lower face not cut out.
- 24" Hemlock bears S37½°E 23 lks.; now 24" stub 7 ft. high, scribes T3N R7W S16 visible.
- 9" Hemlock bears S66°W 17 lks.; now 10" uproot out of place scribes S17 visible, roots in place.
- 6" Hemlock bears N42°W 23 lks.; now 10" stub 15 ft. high scribes S8 visible, rest not exposed.

RESTORED

Set 1½" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T3N R7W S8 S9 S17 S16 1954 RE 2311," 34 inches in ground, in mound of stone, and from which a:

- 17" Hemlock bears S51°E 186.0 ft.; scribed T3N R7W S16 BT.
- 11" Hemlock bears N80°E 173.8 ft.; scribed T3N R7W S9 BT.
- 48" Fir stump bears N60°W 97.8 ft.; scribed T3N R7W S8 BT RE 2311.
- 60" Fir stump bears S88°W 105.2 ft.; scribed T3N R7W S17 BT.

Oregon State Board of Forestry metal location poster on 48" fir stump BT.

Also poster on 30" Hemlock N25½°W 23.3 ft. of pipe. 4" x 4" x 72" white Cedar post 1ft. SE of pipe.

Dated March 23, 1954.

Restored by Richard Morris under my direction.
Richard Morris, Compassman



Present and witnessed by Robert Cowan, Lloyd Geraths