

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to Sections 23, 24, 25 and 26 T2N, R7W, W.M. Tillamook County, Oregon.

ORIGINAL

Stone, 18"x12"x12", in place, 2 notches on South and one on East edges, from which a:

- 18" Hemlock bears N49°E 37 lks.; now 20" stub 4 ft. high, badly burned and rotted.
- 20" Fir bears S67°E 16 lks.; now 24" snag, N and other scribes visible around edge of burnt out face.
- 22" Fir bears S52°W 32 lks.; now 29" snag scribes T2N R7W S26 exposed.
- 18" Hemlock bears N59°W 63 lks.; now 20" stub 9 ft. high, edges of burnt out face visible.

RESTORED

Erected mound of boulders around original stone, from which a:

- 18" Fir snag bears S24 $\frac{1}{2}$ °W 14.4 ft.; scribed T2N R7W S26 BT.
- 28" Fir snag bears S42°E 32.3 ft.; scribed T2N R7W S25 BT.
- 22" Fir snag bears N75°E 99.6 ft.; scribed T2N R7W S24 BT.
- 20" Fir snag bears N74°W 63.0 ft.; scribed T2N R7W S23 BT RE 2311.

Oregon State Board of Forestry metal location poster on 18" fir snag BT.

Oregon State Board of Forestry metal location poster on original 22" Fir S52°W.

Set 4"x4"x72" white Cedar post 2 ft. NE of corner stone.

Dated November 17, 1954.

Restored by Richard Morris under my direction.
Richard Morris, Eng. Aide



Present and witnessed by Claude Weikel, Forest Logan and Lloyd Geraths