

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One quarter corner common to Sections 24 and 25, T2N, R7W.W.M.,
Tillamook County, Oregon.

ORIGINAL

Stone, 20"x12"x9", (found $\frac{1}{4}$ facing up), from which a:

14" Fir bears N31°E 16 lks.; now 22" uproot,
root hole in place, burnt out face.

15" Fir bears S13°W 30 lks.; now 14" stub 20 ft. high,
face burnt out.

RESTORED

Set stone upright with $\frac{1}{4}$ on North face, and erected mound of
stone around it, from which a:


24" Double fir bears S27 $\frac{1}{2}$ °W 34.1 ft.; scribed $\frac{1}{4}$ S25 BT
RE 2311.

17" Fir snag bears N56°E 29.1 ft.; scribed $\frac{1}{4}$ S24 BT.

Oregon State Board of Forestry metal location poster on 24" Fir BT.
C-Z metal location poster on original 15" Fir BT.
Set 2"x4" x72" white Cedar post 3 ft. SW of corner stone.
Corner falls on South side of ridge top.

Dated November 17, 1954.

Restored by Richard Morris under my direction.
Richard Morris, Eng. Aide



Present and witnessed by Claude Weikel, Forest Logan
and Lloyd Geraths