

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to Sections 19, 20, 29 and 30
T2N, R6W, W.M., Tillamook County, Oregon.

ORIGINAL

15"x12"x10" stone, now missing, from which a:

- 36" Fir bears N42°E 41 lks.; now 40" by 15 ft. stub, faces unexposed.
- 30" Hemlock bears S45°E 54 lks.; now 34" by 20ft. stub, part of scribes TN remaining.
- 24" Hemlock bears S10°W 25 lks.; now just roots remaining in place.
- 30" Hemlock bears N34°W 55 lks.; now 20" snag scribes T2 R6 S remaining.

RESTORED

Set 1½" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T2N R6W S19 S20 S29 S30 1954 RE 2311," 30 inches in ground, in mound of stone, and from which a:

- 6" Fir bears S15°W 35.0 ft.; scribed T2N R6W S30 BT.
- 6" Fir bears N60°E 29.0 ft.; scribed T2N R6W S20 BT.
- 24" Fir snag bears N39°W 50.1 ft.; scribed T2N R6W S19 BT RE 2311.
- 5" Fir bears S68°E 47.0 ft.; scribed T2N R6W S29 BT.

Oregon State Board of Forestry metal location poster on Original 30" Hemlock BT N34°W.

Oregon State Board of Forestry metal location poster on 6" Fir BT S15°W.

Set 4"x4"x84" white Cedar post 1 ft. SE of pipe.

Dated December 17, 1954.

Restored by Arnold G. Gibson under my direction.
Arnold G. Gibson, Ass't. Engr.



Present and witnessed by Richard Morris
Claude Weikel
Forrest Logan
Lloyd Geraths