

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One quarter corner common to Sections 16 and 17, T2N, R8W, W.M., Tillamook County, Oregon

ORIGINAL

14"x10"x9" stone, 1/4 on face, found out of place, from which a:

18" Cedar bears S43°W 38 lks.; now 30" uproot, face burnt out.

30" Fir bears N70°E 11. lks.; now 36" stump, 1/4 scribes visible, BT face unexposed.

RESTORED

Set stone back in place with 1/4 on W side and in mound of rock, from which a:

41" Fir stump bears S32°W 34.3 ft.; scribed 1/4 S17 BT RE 2311.

24" Cedar snag bears S59 1/2°E 77.1 ft.; scribed 1/4 S16 BT.

Oregon State Board of Forestry metal location poster on 24" Cedar snag BT.

Oregon State Board of Forestry metal location poster on original 30" Fir BT.

Dated December 14, 1954.

Restored by Arnold G. Gibson under my direction.
Arnold G. Gibson, Ass't. Eng.



Present and witnessed by Richard Morris and Forest Logan