

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to Sections 21, 22, 27 and 28
T2N, R8W., W.M., Tillamook County, Oregon.

ORIGINAL

- 6" Fir, now 5"x4" high stub, from which a:
 - 20" Fir bears N70°E 29 lks.; now 20" by 40" snag, badly burnt.
 - 18" Hemlock bears S30°E 70 lks.; now 22" by 30" snag, scribes N R8 visible, lower face unexposed.
 - 24" Hemlock bears S60°W 36 lks.; now 26" by 35" snag BT scribes remaining.
 - 42" Larch bears N34°W 68 lks.; now missing, slide area.
 - 41" Fir stump bears N66°W 41.9 ft.; scribes W and BT visible in old faces.

RESTORED

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T2N R8W S21 S22 S27 S28," in place of original 6" tree, 33 inches in ground, in mound of rock, and from which a:

- 24" Fir snag bears S44°W 26.1 ft.; scribed T2N R8W S28 BT RE 2311.
- 31" Fir snag 35 ft. high bears N47°W 22.6 ft.; scribed T2N R8W S21 BT.
- 35" Fir stump bears N18°E 9.4 ft.; scribed T2N R8W S22 BT.
- 32" Fir snag bears S60°E 34.0 ft.; scribed T2N R8W S27 BT.

Oregon State Board of Forestry metal location poster on 32" Fir snag BT.
Set 4"x4"x84" white Cedar post 1.5 ft. NW of pipe.

Dated December 14, 1954.

Restored by Richard Morris under my direction.
Richard Morris, Engr. Aide.



Present and witnessed by Lloyd Geraths
Claude Weikel
Forest Logan