

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One quarter corner common to Sections 21 and 28, T2N, R8W, W.M., Tillamook County, Oregon.

ORIGINAL

42" Fir, now 40 ft. snag  $\frac{1}{4}$  S scribes on N and S sides, from which a:

20" Hemlock bears N5°E 11 lks.; now just roots remaining in place.

10" Hemlock bears S32°W 47 lks.; now just roots remaining in place.

RESTORED

Used center of original corner tree, from which a:

36" Fir snag bears N83°W 21.9 ft.; scribed  $\frac{1}{4}$  S21 BT RE 2311.

48" Fir snag bears S36°W 55.0 ft.; scribed  $\frac{1}{4}$  S28 BT.


Oregon State Board of Forestry metal location poster on 36" Fir snag BT.

Oregon State Board of Forestry metal location poster on 48" Fir snag 300 ft. S22°E on N bank of log road.

Set 4"x4"x84" white Cedar post 3 ft. S of corner tree.

Dated December 14, 1954.

Restored by Richard Morris under my direction.  
Richard Morris, Engr. Aide



Present and witnessed by Lloyd Geraths  
Forest Logan  
Claude Weikel