

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to Sections 23, 24, 25 and 26,  
T.1N, R.9W, W.M., Tillamook County, Oregon.

ORIGINAL

Basalt stone 24"x10"x8", now in place 2 notches on S side  
and 1 on E from which a:

- 54" Hemlock bears N69°W 45 lks.; now 61" snag, scribes  
TLN R9W S2 visible, rest rotted out.
- 19" Spruce bears N21°E 33 lks.; now 56", scribes TLN  
R9W visible, rest rotted out.
- 12" Hemlock bears S51°E 97 lks.; now 30", face unexposed.
- 18" Hemlock bears S29°W 31 lks.; now 30" snag, trace of  
scribes visible on badly rotted face.

(All original BT's check for distance when measured by slope  
distance.)

RESTORED

Original corner stone is 6 inches in ground, from which a:

- 37" Hemlock bears S73°W 8.2 ft.; scribed TLN R9W S26 BT  
RE 2311.
- 10" Cedar bears S75°E 32.3 ft.; scribed TLN R9W S25 BT.
- 10" Hemlock bears N63°E 36.6 ft.; scribed TLN R9W S24 BT.
- 14" Hemlock bears N11°W 29.3 ft.; scribed TLN R9W S23 BT.

Set 4"x4"x72" white Cedar post 1' NW of cor. stone.  
Oregon State Board of Forestry metal location poster on 37" Hem-  
lock BT.  
Oregon State Board of Forestry metal location poster on 60" Spruce  
on S edge cat Rd., approx. 2 chs. N.

Dated March 11, 1955.

Restored by Richard Morris under my direction.  
Richard Morris, Engr. Aide



Present and witnessed by Lloyd Geraths  
Claude Weikel