

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One-quarter section corner common to Sections 6 and 31,
T. 3 & 4 N, R. 6 W., W.M., Clatsop and Tillamook
Counties, Oregon.

ORIGINAL

Stake, now missing, from which a:

36" Cedar bears S5°E 34 lks.; now 38" uproot, roots
and root hole in place, part of scribes $\frac{1}{4}$ S BT visible.
20" Hemlock bears North 60 lks.; now missing.

RESTORED

Set 1 $\frac{1}{2}$ " x 36" galvanized iron pipe with 3" bronze cap
marked "OREGON STATE BOARD OF FORESTRY $\frac{1}{4}$ S31 S6
1955 RE 2311," 33 inches in ground, in mound of
stone, and from which a:

10" Hemlock bears N46°W 36.0 ft.; scribed $\frac{1}{4}$ S31 BT RE 2311.
44" Fir stump bears S10°W 37.3 ft.; scribed $\frac{1}{4}$ S6 BT.

Set 4"x4"x70" white Cedar post 1' NW of pipe.

Oregon State Board of Forestry metal location poster on
10" Hemlock BT.

Oregon State Board of Forestry metal location poster on
4"x4"x72" white Cedar post on E edge Rd. approx. 585' W.
General Land Office poster on 44" Fir stump BT.

Dated March 11, 1955

Restored by Richard Morris under my direction.
Richard Morris, Engr. Aide



Present and witnessed by Lloyd Geraths
Forrest Logan
Claude Weikel