

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to Sections 18,19,13 and 24,
T. 1N., R. 7-8 W., W.M., Tillamook County, Oregon.

ORIGINAL

Post, now missing, from which a:

- 6" Hemlock bears N24°W 37 lks.; now 6" uproot, badly burnt
- 8" Hemlock bears N63°E 41 lks.; now 24" 7 ft. high stub, portions of scribes visible on edge burnt out face.
- 5" Hemlock bears S31°E 40 lks.; now missing.
- 7" Hemlock bears S67°W 47 lks.; now 12" uproot under log pile, roots in place.

RESTORED

Set 1½" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY TIN R7W R8W S13 S24 S18 S19 1955 RE 2311," 34 inches in ground, in mound of stone, and from which a:

- 52" Fir stump bears S85°W 60.8 ft.; scribed TIN R8W S24 BT.
- 59" Fir stump bears S21°E 37.8 ft.; scribed TIN R7W S19 BT RE 2311.
- 50" Fir stump bears N43°E 63.0 ft.; scribed TIN R7W S18 BT.
- 54" Fir stump bears N21°W 80.2 ft.; scribed TIN R8W S13 BT.

Set 4" x 4" x 72" white painted Cedar post 2 ft. SE of pipe.

Oregon State Board of Forestry metal location poster on 59" Fir stump BT.

Dated May 17, 1955.

Restored by Arnold G. Gibson under my direction.
Arnold G. Gibson, Assistant Engineer



Present and witnessed by Richard Morris
Lloyd Geraths
Forrest Logan
Robert Strum