

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One quarter corner common to Sections 7 and 18,
T3N, R6W, W.M., Tillamook County, Oregon.

ORIGINAL

Post, now missing, found rotted stake point, from which a:

- 18" Hemlock bears N80°E 34 lks.; now 12" 4 ft. high stub, bottom of original face remaining, badly burnt.
- 48" Fir bears S23½°E 10 lks.; now 42" stump, scribes ¼ S visible, lower face unexposed.

RESTORED


Set 1½" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY ¼ S7 S18 1955 RE2311," 33 inches in ground, in mound of stone, and from which a:

- 10" Fir bears N21°W 61.5 ft.; scribed ¼ S7 BT RE2311.
- 7" Fir bears S18°W 38.0 ft.; scribed ¼ S18 BT.

Set 4"x4"x60" white painted Cedar post 1.5 ft. SE of pipe.
Oregon State Board of Forestry metal location poster on 7" Fir BT.
Old poster on 48" Fir stump S78°E 29 lks.
Also poster on 12" Fir on W edge road approximately 1090 Ft. W.

Dated June 3, 1955.

Restored by Richard Morris under my direction.
Richard Morris, Engineering Aide



Present and witnessed by Lloyd Geraths
Forest Logan
Robert Sturm