

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One quarter corner common to Sections 17 and 20,
T3N, R6W, W.M., Tillamook County, Oregon.

ORIGINAL

Water worn stone 16"x12"x8", in place, from which a:

- 30" Hemlock bears N70°45'E 51 lks.; now 16" 4 ft. high stub,
original axe work on edges burnt out face.
- 60" Fir bears S21°E 10 lks.; now 54" stump, scribe $\frac{1}{4}$ visible,
lower face unexposed.
- 60" Fir bears N21°W 4 $\frac{1}{2}$ lks.; now 48" stump, scribes $\frac{1}{4}$ S BT
visible.

RESTORED

Erected mound of rock around $\frac{1}{4}$ stone from which a:

- 6" Fir bears N17°E 43.5 ft.; scribed $\frac{1}{4}$ S17 BT RE2311.
- 5" Fir bears S50°E 4.9 ft.; scribed $\frac{1}{4}$ S20 BT.

Set 4"x3"x72" white painted Cedar post 2' ft. SW of corner.
Oregon State Board of Forestry metal location poster on 5" Fir BT.
Also poster on 4"x3"x72" white painted Cedar post on W edge road
64.1 ft. West of corner.

Dated June 9, 1955.

Restored by Richard A. Morris under my direction.
Richard A Morris, Engineering Aide



Present and witnessed by Robert Sturm.